

TEST REPORT
IEC/EN 60335-1
Safety of household and similar electrical appliances

Report Reference No.: 9S061
 Date of issue: 03.05.2010
 Total number of pages: 77

Testing Laboratory: INTRATest GmbH
 Address: Reusswehrstrasse 1
 CH – 5412 Gebenstorf
 Switzerland



STS 355

Applicant's name: Mariner 3S AG
 Address: Brunnmattstrasse 7
 5236 Remigen
 Switzerland

Test specification:

Standard: IEC 60335-1:2001 (4. Edition) (incl. Corrigendum 1:2002) +
 A1:2004 + A2:2006 (incl. Corrigendum 1:2006) and/or
 EN 60335-1:2002 + A1:2004 + A11:2004 + A12:2006 + A2:2006
 According to EN 60335-2-41:2003 + A1:2004
 Test procedure: CE
 Procedure deviation: 6.2
 Non-standard test method: N

Test Report Form No.: IECEN60335_1B
 Test Report Form(s) Originator: Nemko AS
 Master TRF: Dated 2006-10



Copyright © 2006 IEC System for Conformity Testing and Certification of Electrical Equipment (IECEE), Geneva, Switzerland. All rights reserved.

This publication may be reproduced in whole or in part for non-commercial purposes as long as the IECEE is acknowledged as copyright owner and source of the material. IECEE takes no responsibility for and will not assume liability for damages resulting from the reader's interpretation of the reproduced material due to its placement and context.

This report is not valid as a CB Test Report unless signed by an approved CB Testing Laboratory and appended to a CB Test Certificate issued by an NCB in accordance with IECEE 02.

This report is not valid as a CCA Test Report unless signed by an approved CCA Testing Laboratory and appended to a CCA Test Certificate issued by an NCB in accordance with CCA

Test item description: Cleaning system (robot) for swimming pools
 Trade Mark: N
 Manufacturer: See Applicant
 Model/Type reference: clubliner
 Ratings: Pri.: 100-240V, 50-60Hz, 4A
 Sec.: 28VDC, 14A

Testing procedure and testing location:	
<input type="checkbox"/> CB/CCA Testing Laboratory: Testing location/ address	
<input type="checkbox"/> Associated CB Laboratory: Testing location/ address	
Tested by (name + signature)..... Approved by (+ signature).....	
<input checked="" type="checkbox"/> Testing procedure: CE Tested by (name + signature).....	Ralf Gasser 
Approved by (+ signature).....	Erich Forster 
Testing location/ address	Reusswehrstrasse 1 CH – 5412 Gebenstorf Switzerland
<input type="checkbox"/> Testing procedure: WMT Tested by (name + signature)..... Witnessed by (+ signature)	
Approved by (+ signature)..... Testing location/ address	
<input type="checkbox"/> Testing procedure: SMT Tested by (name + signature)..... Approved by (+ signature)..... Supervised by (+ signature).....	
Testing location/ address	

Summary of testing:	
Tests performed (name of test and test clause): The model clubliner is in accordance to standards listed on page 1.	Testing location: See above
Summary of compliance with National Differences: Switzerland	
Copy of marking plate:	
	
